North America Emission Control Area Fuel Oil Non-Availability Report
ECA0100
1 2
##

##(Include Double Pound for comments not form fields)
##Report Form ID Ship Operator Name IVELIN TENEV

3 4 5 6 7

Vessel Name Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice STRATEGIC SYNERGY SNG 9648087 7/22/2014 BUENAVENTURA

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption NIL BUENAVENTURA

11 12 13

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted Date of Entry in the ECA 8/2/2014

Time of Entry in the ECA Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion 12:00 LT 1.47; 1.44 Projected Hours on Main Propulsion 96 HRS

Name of First POC Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC? VANCOUVER BC Vancouver BC Vancouver BC

Number of fuel suppliers contacted at First POC Name of Second POC Compliant Fuel Oil at Second POC?

23

24

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months? REVERTING YES

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms?

1 N/A

30

Number of Submitted Reports Designated Corporate Official Name Designated Corporate Official E-mail N/A PLS ADVISE Designated Corporate Official E-mail PLS ADVISE

34 35

Designated Corporate Official Phone Number Description of Actions to Achieve Compliance PLS ADVISE